

VEEDER-ROOT PRE-SET COUNTER ONE-TIME COMPLETE SETUP

1. Press "E" & "5" together during Power Up (as you apply power to the Counter).
DISPLAY READS "F0 0"
2. Press "E" repeatedly until "F6" appears
PRESS 1 REPEATEDLY UNTIL "ON" APPEARS
3. Press "E" repeatedly until "F10" appears
PRESS 1 REPEATEDLY UNTIL "0" APPEARS
4. Press "E" so that "F11" appears
PRESS 1 SO THAT "1" APPEARS
5. Remove Power From The Counter.

TO ENTER DESIRED PRE-SET COUNT

1. Apply power to the Counter
2. Press "R" (6 and 4) together to reset the Counter To "0"
3. By hand, pull a strip of labels back and forth through the Label Sensor Gap
4. Turn the black Sensor Adjustment Knob to the mid-point of the range where labels are detected / counted on the Counter
5. The Display will now indicate the number of labels that pass by the sensor
6. Press "E" & "1" at the same time
7. Press the desired count for each digit
8. Press "E" to Enter the count into memory
9. When the Preset Count is reached, the Rewinder with External Halt Control will stop
10. Press "R" (6 and 4) at the same time to Reset the Counter To "0". The Rewinder will start again.

CounterVeederRoot.DOC